FINAL RANDOM INSPECTION

COMPRESSION SOFAS

Pre-shipment quality inspection report

MODEL SB-B-COMP-LZSF-BR · 5 PCS SAMPLED

All 60 units finished and packed. Five sampled, zero defects. One data point to update before release.



OVERALL RESULT	QUANTITY	INSPECTED	ROUTE
PASS (C) CONDITIONAL PASS	60 PCS	2026.01.07	HANGZHOU → AUSTRALIA

Client copy — client, supplier, factory address, order number, staff names and the carton barcode are masked throughout this document.

01 Verdict at a glance

The verdict, the numbers, and the one thing worth acting on.

AT A GLANCE

OVERALL RESULT

PASS (C)

Accepted — one data point to update

The product itself is fine. Only the SKU record needs updating.



60 PCS
Order quantity · 100% packed

5 PCS
Sample size · single normal plan

0 DEFECTS
Critical / major / minor

12 CHECKPOINTS 9 evaluated · 3 not applicable

Quantity	• PASS	Barcode	• PASS
Colour / style	• PASS	On-site tests	• PASS
Workmanship	• PASS	Measurements	• CONDITIONAL
Packing	• PASS	Critical components	• N/A
Shipping marks	• PASS	Certificates	• N/A
Labels	• PASS	Client requirements	• N/A

THREE THINGS TO KNOW

01
Appearance & workmanship
Five samples checked one by one. No loose threads, stains, shading or damage. AQL: accepted.

02
Measurements
Length measures 102.5 cm against 80 cm in the SKU file. A record gap, not a defect.

03
Packing & tests
One unit per carton, five-ply board. Drop, function, rubbing, loading and tape tests all passed.

Not evaluated: critical component data, certificate verification and client-specific requirements — not applicable to this programme (N/A).

02 The product

What was inspected, where, and under which sampling plan.

CLIENT · SUPPLIER · MANUFACTURER	Masked	REPORT NUMBER	VT260112522
INSPECTION LOCATION	Hangzhou, Zhejiang, China (factory site)	DATE OF ISSUE	2026-01-08
ORDER NUMBER	QA-****-3666 | PO-****-29095	DESTINATION	Australia
MODEL	SB-B-COMP-LZSF-BR	SERVICE	FRI — final random inspection
PRODUCT	Compression sofas	STANDARD	ISO 2859-1 / ANSI Z1.4
ORDER QUANTITY	60 pcs · 100% finished / 100% packed	INSPECTION LEVEL	General II · AQL 0 / 2.5 / 4.0
DATE OF INSPECTION	2026-01-07	SAMPLE / STAFF	5 pcs · H. L. · S. Z.

PRODUCT VIEWS



Front
As opened — warm mustard nap



Side
Lounge curve, generous seat depth



Rear 3/4
Panel quilting, even stitching

ABOUT THIS PRODUCT

Vacuum-compressed and rolled for shipping; expands into a single-seat lounge sofa. Soft nap fabric, quilted panels and a non-slip base cloth.

HOW THIS INSPECTION RAN

01 **Quantity**
All 60 pcs counted in

02 **Workmanship**
5 pcs inspected piece by piece

03 **Packing**
Carton, marks and labels checked

04 **Measurements**
9 data points compared

05 **On-site tests**
5 tests performed

03 Appearance & workmanship

The parts a customer notices first — checked stitch by stitch.

APPEARANCE



Quilting
Panel depth consistent, no collapse



Seams
Even stitch density, no loose thread



Creases
Recovers cleanly after compression



Base
Non-slip cloth, binding flat



Front
Quilting symmetrical, edges straight



Rear
Balanced shape, no bulging

AQL RESULT

All five sample units inspected: **0 critical / 0 major / 0 minor — ACCEPT**

AQL: critical 0 (not allowed) · major 2.5 · minor 4.0. Each unit was checked visually against the golden sample and the colour swatch; no failure was triggered.

DEFECTS FOUND

CRITICAL	not allowed	0
MAJOR	Ac 0 / Re 1	0
MINOR	Ac 0 / Re 1	0

WORKMANSHIP CHECK

- ✓ Even stitching
- ✓ Full quilting
- ✓ Symmetry
- ✓ Edge binding
- ✓ Labeling
- ✓ No shading

Inspector's note — fabric nap, quilt depth and seam tension are amplified once a vacuum-compressed sofa is opened. All five units matched the golden sample in colour, hand-feel and workmanship; no visible shading was found.

- All photos were taken on site on 2026-01-07; only cropping and corner rounding applied.

04 Packing & markings

One unit per carton, five-ply board — and everything printed on it.

PACKING

PACKING SPEC

CARTON QUANTITY	1 pc · no inner carton
CARTON SIZE	37 × 36.8 × 91.7 cm
GROSS WEIGHT	10.7 kg (record 10.5 kg)
BOARD	5-ply corrugated
CARTON	New export carton
SEALING	Glue + transparent gummed tape
INNER PACKING	Vacuum bag + PE film, no EPS

COMPLIANCE No EPS foam used — meets Australian packaging requirements.



As packed
Vacuum-compressed roll, wrapped in PE film

CARTON & SEAL



Rolled
Vacuum-compressed, film wrap



Pre-pack
Warning labels facing out



Sealed
5-ply board, tape flat

MARKS & LABELS



Barcode
Scanned on site · code masked



Warning label
Five-step unpacking instruction



Cautions label
Environment and safety notes

MARKINGS CHECKED

Shipping mark matches the SKU file. Master carton barcode scans clean. Warning and caution labels are in English, complete and centred.

- The barcode itself is masked in this client copy; the scan result is confirmed above.

05 Measurements & weight

The carton is within tolerance. The product record is not — here is why.

MEASUREMENTS

SPEC VS ACTUAL DEVIATION negative = smaller than record



ITEM	SPEC	ACTUAL	Δ	STATUS
Carton length	37.0	37.0	0.0%	IN
Carton width	37.0	36.8	-0.5%	IN
Carton height	90.0	91.7	+1.9%	IN
Gross weight	10.5	10.7	+1.9%	IN
Product length	80.0	102.5	+28.1%	OUT
Product width	90.0	87.5	-2.8%	IN
Height A	35.0	29.0	-17.1%	OUT
Height B	70.0	68.0	-2.9%	IN
Net weight	8.5	9.0	+5.9%	IN

Tolerance: carton ±8%, product ±5%. Spec values are taken from the SKU detail file; height is recorded as two positions (35 / 70 cm).

Why PASS (C)?

Carton size and gross weight sit inside the ±8% tolerance. Product length measures 102.5 cm against 80 cm on file (+28.1%); height A measures 29 cm against 35 cm (–17.1%).

The inspector's reading: this is a compression sofa, and the opened product is measured on a different basis than the record. The record is stale — not a production defect.

ACTION

1. Update the SKU size and net weight
2. Agree one measuring method
3. Re-check on the next order



Measured on site

Steel tape, both ends aligned

06 On-site tests

Five tests performed on site, with photographic evidence.

#	TEST	SAMPLE	METHOD	RESULT
01	Mail box drop	1 box	One corner, three edges, six faces; 10.7 kg → 24 in (61 cm)	PASS
02	Functional	2 pcs	Opened and used as designed	PASS
03	Rubbing	2 pcs	Wet cloth, 15 seconds, air dried	PASS
04	Loading	2 pcs	No structural failure under load	PASS
05	3M tape adhesion	2 pcs	No lifting after peel	PASS



Drop



Rubbing



Function



Loading



3M tape

CONCLUSION

These 60 units are good to ship.

Product, packing, markings and on-site tests all meet the requirements. The only open item is the size data in the SKU record.

Release is recommended once the SKU record is updated.

NEXT 30 DAYS

- Sync SKU length, width, height and net weight
- Agree the opened / compressed measuring basis
- Keep the same AQL plan for bulk production

60	5	0	9/12	5/5
UNITS READY TO RELEASE	UNITS SAMPLED	DEFECTS FOUND	CHECKPOINTS SCORED	ON-SITE TESTS PASSED

INSPECTOR	REVIEWER	DATE OF ISSUE
H. L.	S. Z.	2026-01-08

This report reflects the findings at the time and place of inspection. It does not relieve the seller or manufacturer of contractual liabilities and does not evidence shipment.
Client, supplier, factory address, order number and staff details have been masked for this client copy.